FUTURE GRAPHICS

Receiving Inspection Criteria
HP 51649A Cartridge

SIDE VIEW



No cracks or openings at joint.

No cracks in the plastic case.

CONTACT SIDE VIEW



No delamination or ink under flex circuit beyond this point.



No cracks.

No separation or breaks of copper conductor.

Ink under delaminated flex circuit.

Maze hole cover not delaminated.



BOTTOM VIEW

No ink or delamination under flex circuit.



No deep scratches or holes in the nozzle plate (nozzle plate not lifted and in place... it must be there).



Plate missing

Ball old style.



No ink leaking out of vent/bag hole or around it.

New maze cover.

Old maze cover.



No cracks in maze cover.

Check air bags for leaking.

For More Information Please Contact Ink Jet Inspection Department:
1175 Aviation Place San Fernando, CA 91340 • Toll Free: 800 394-9900 • 818 837-8100
Visit us Online at: www.futuregraphicsllc.com