FUTURE GRAPHICS

Receiving Inspection Criteria for Lexmark Black Cartridge & Compatible

Original lexmark label.

SIDE VIEW



No evidence of rebonding cap.

NOZZLE PLATE



No holes drilled into cap other than OEM vent.

No cracks or holes in the plastic case.



No delamination from plastic case or ink under flex circuit beyond this point.

CONTACT SIDE VIEW

No holes, deep scratches, ink under flex circuit or delamination.

NOZZLE PLATE ENLARGED VIEW



No deep scratches or holes in nozzle plate.

No ink under flex circuit.

NO NOZZLE PLATE



Nozzle plate must not be lifted or missing.

For More Information Please Contact Ink Jet Inspection Department:
1175 Aviation Place San Fernando, CA 91340 • Toll Free: 800 394-9900 • 818 837-8100
Visit us Online at: www.futuregraphicsllc.com