

Receiving Inspection Criteria Canon BC-20 Cartridge

CONTACT SIDE VIEW



PCB not cut or evidence of replacement. No corrosion on contacts.

SIDE VIEW



GENERAL NOTES:


Inspect for remanufacturing marks on the cartridge.

No cracks in case.

No additional holes drilled into case.

Original plug in place.

BOTTOM VIEW



Nozzle plate not scratched or lifted.

No gap or delamination.