

Receiving Inspection Criteria HP 1823A/41A/78A/6625A Cartridges

No delamination or flex cable from plastic case beyond this point.

SIDE VIEW

HP label must be on cartridge


No cracks in the plastic case.

CONTACT SIDE VIEW


No holes or deep scratches in the nozzle plate. No delamination.

No corrosion on the contacts. no cuts in the flex cable.

General Notes:
No ink leakage from the cartridge case. (bag may be damaged)





No ink under flex circuit in this area.



No delaminated conductors for flex circuit.

Nozzle Plate Side

Nozzle plate not lifted, loose or missing.



Plugs not removed no additional holes in top.