








Receiving Inspection Criteria HP 51626A Cartridge





No deep scratches or holes in the nozzle plate (nozzle plate not lifted and in place... it must be there).



Ink under delaminated flex circuit.

No ink leaking out of vent/bag hole or around it.



Check air bags for leaking.